

| REFERENCE | designation                                                           |
|-----------|-----------------------------------------------------------------------|
| BM-032    | BUTEE D'EMB CITR.C-CROSSER-MITSUBISHI,LANCER-COLT                     |
| BMT-386   | POMPE DE FREIN TOYOTA LAND CRUISER (J12) 4°                           |
| BN-067    | BUTEE D'EMB NISSAN PICK-UP(D21)(D22) 2.5D                             |
| BS-009A   | BUTEE D'EMB SUZUKI BALENO-SWIFT II-SUPER-CARRY                        |
| BT-117    | BUTEE D'EMB TOYOTA AVENSIS(T22)-COROLLA E12                           |
| BY-009    | BUTEE D'EMB HYUNDAI ACCENT-IX 35-TUCSON-CARENS III-SPORTAGE=804256    |
| BY-013    | BUTEE D'EMB HYUNDAI ACCENT III-I20-I40 =804231                        |
| CMT-138   | EMMETT D'EMB. TOY AURIS (E15) - COROLLA (E15) 1.4D                    |
| CMT-141   | EMETTEUR D'EMBAYAGE TOTYOTA COROLLA (E12)-VERSO 2° D 2004--->2007     |
| CMTS-011  | EMETTEUR D'EMB TOYOTA HILUX VIII 2.4 D 4WD -2015--                    |
| CRT-085   | RECEPTEUR D'EMB TOYOTA AVENSIS-COROLLA E12-RAV 4 II-III=ASH-85-02-230 |
| CSCY-002  | BUT.HYD. HYU.IX35TUCSON,KIACARENS ,SPORTAGE 2.0CRDI=804559=5100151100 |
| DM-034U   | DISQUE.EMB D.225(23D) MITSUBISHI L200-L300-PAJERO I/II                |
| DS-009U   | DISQUE EMB SUZUKI CARRY CAMIONETTE 99++/ JIMNY 2004++                 |
| FDY-005   | VOLANT MOTEUR HYUNDAI SANTA FE D.260 2,2L AN : 2006 -...=4150285100   |
| FDY-007   | VOLAN.MOTEUR HYUND.TUCSON-KIA CARENS III-SPORTAGE 2.0CRDI =4150273100 |
| KG-035A   | KIT D'EMB D.230,24D -ISUZU DMAX(8DH) 2007+++                          |
| KH-085    | KIT D'EMB D.222/24D HONDA ACCORD VIII 2.4 i -2008-2015=6223471000     |
| KM-004A   | KIT D'EMB(3P) D.190/20D,MITSUBISHI COLT-LANCER                        |
| KM-008    | KIT D'EMB D.200(3P)MITS.COLT III-GALANT III-LANCER IV ESS.= 801958    |
| KM-048C   | KIT.EMB(3P)D.250,23D,MITS.PAJEROII 2.8TD=CM905+DM068(ressort)=KM-078A |
| KM-091B   | KIT D'EMB. (3P) D250,23D,MITSUBISHI L200 TRITON 2.5D =KM-092A=828807  |
| KN-094    | KIT D'EMB 3P NISSAN PRAIRIE PRO 2.4 I D.227-24 DENT                   |
| KN-122A   | KIT D'EMB (3P ) Diam . 240 , 24 D , NISSAN PATROL 2.8 TD=826438       |
| KN-205    | KIT D' EMB (3P) D 250,24 D,NISSAN PICK UP(D22) 2.5 DI 03/2002----     |
| KN-216R   | KIT D'EMB(2)D.220/26D,NISSAN JUKE-NOTE-QASHQAI 1,6 ESS.=6223199090    |
| KO-012    | KIT D'EMB(3P)D.215(24D) DAEWOO LANOS-NUBIRA = 821414                  |
| KS-013B   | KIT D'EMB(3P)D.190(18D)SUZUKI BALENO-1,6 ESS. =826200                 |
| KS-025    | KIT D'EMB D.200,20D(3P) SUZUKI VITARA 1.9D 95----2004 =821326         |

| REFERENCE | designation                                                           |
|-----------|-----------------------------------------------------------------------|
| KS-036A   | KIT D'EMB(3P) D.190(20D), SUZUKI CARRY 1.3 ESS                        |
| KT-088C   | KIT EMB 3P D.239/21D TOYOTA LAND CRUISER J7 90-93=801494=KT-088B      |
| KT-100A   | KIT.EMB(3P)D.220/21D,TOY.AVENSIS(T22)-COROLLA(E12) 1.6 ESS.=828061    |
| KT-124B   | KIT D'EMB(3P)D.280(21D) TOYOTA LAND CRUISER 4,2D                      |
| KT-233A   | KIT D'EMB D.200(3P)21D TOYOTA YARIS 1.3 ESS. = 826622                 |
| KT-273B   | KIT D'EMB(3P)D.200(19D)TOYOTA YARIS ESS.=826030/842030=KT-273C        |
| KT-352A   | KIT EMB 3P TOYOTA YARIS COROLLA1.4 VVT-I D.203 REMP PAR KT-352B       |
| KT-374    | KIT D' EMB (3P) D.236/21D,TOYOTA VIGO - HIACE IV 2.4 TD               |
| KY-025    | KIT D'EMB D.240(3P)23D HYUNDAI H1/STAREX 2.5TD = 826331               |
| KY-086    | KIT D'EMB (3P)D.240(23D),KIA K2500(SD) 2.5 D-PREGGIO 2003-->=826335   |
| KY-088A   | KIT D'EMB D.181(24D)-KIA PICANTO-HYUNDAI I10-1.0, 1.1=822728=61830160 |
| KY-110A   | KIT D'EMB 3P D.215/20D KIA CERATO-HYUNDAI i30-ix20 1.6 -2010--=KK-025 |
| RH-011    | RECEPTEUR D'EMB HONDA JAZZ II 1.3 ESSENCE                             |
| RY-004    | RECEPTEUR D'MB HYUNDAI HI 2.5D=41700-43150                            |
| WPM-029   | POMP A EAU MITSUBISHI PAJERO 2,5TD - L200 = H-212=H206=GWM52=240701   |
| WPT-001B  | POMPE A EAU TOYOTA HILUX II-HIACE IV = GWT79                          |